




# NO LEFT TURN AT 1550 NORTH 900 EAST

By Vern Keeslar, Traffic Manager

May 1, 2024



# Location Map



# Options Discussed with BYU

- Keep existing conditions
- Prohibit left turns during peak hours
- Prohibit left turns all the time
- Install right turn lane and keep left turn movement

# Contact Information

- Vern Keeslar, AICP, Traffic Manager
  - Phone: 801-852-6783
  - Email: [vkeeslar@provo.org](mailto:vkeeslar@provo.org)
  - Address: 1377 South 350 East, Provo, UT 84606

